


Parts Identification Guide

PIH009/0405


TW Plus





TW Plus

- | | |
|------------------------|-----------------------------|
| 1. Motor Drip Cover | 10. Cooling Solenoid Valve |
| 2. Pump Motor | 11. Pressure Relief Valve |
| 3. From Process Sensor | 12. Heater Tank |
| 4. Mixing Tank | 13. Low Pressure Switch |
| 5. Pump Volute | 14. From Process Connection |
| 6. Pump Data Tag | 15. To Process Connection |
| 7. To Process Sensor | 16. Cool Out Connection |
| 8. Heater Element | 17. Cool In Connection |
| 9. Pressure Gauges | |



TW Plus

- 18. Transformer
- 19. Main Terminal Block
- 20. Fuses - Control Power
- 21. Heater Mercury Contactor
- 22. Pump Overload
- 23. Pump Contactor
- 24. Terminal Blocks - Control
- 25. To Process Gauge
- 26. From Process Gauge
- 27. TW Plus Graphic Overlay
- 28. JCI Temperature Controller